

Recall Notification

Today, Daihatsu Motor Co., Ltd. (Daihatsu) notified the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) of a recall of CAST, and PIXIS JOY sold by Toyota Motor Corporation (Toyota).

Previously, Daihatsu had reported to MLIT that there was a possibility of non-compliance with standards, as a result of that investigation, Daihatsu determined that a recall is necessary and has notified MLIT.

1. Vehicles Subject to Recall

Company Name	Model Code	Vehicle Name	Chassis Numbers Containing Vehicles Subject to Recall	Production Period	Number of Vehicles Subject to Recall
Daihatsu	DBA-LA250S 5BA-LA250S 3BA-LA250S	CAST	LA250S-0000067– LA250S-0239782	August 31, 2015– June 9, 2023	239,616
	DBA-LA260S 5BA-LA260S 3BA-LA260S		LA260S-0000065– LA260S-0048615	August 31, 2015– June 9, 2023	48,530
Toyota	DBA-LA250A 5BA-LA250A 3BA-LA250A	PIXIS JOY	LA250A-0000052– LA250A-0028620	August 31, 2016– June 9, 2023	28,324
	DBA-LA260A 5BA-LA260A 3BA-LA260A		LA260A-0000053– LA260A-0006375	August 31, 2016– June 9, 2023	6,270

Notes:

- 1) The range of chassis numbers containing vehicles subject to the recall also includes vehicles that are not subject to the recall. Please contact your local Toyota dealer for details.
- 2) The production period of vehicles subject to the recall is different from the date of vehicle purchase.

2. Status of Defect

The power door lock on the driver's side door may activate during a collision due to insufficient verification of the door lock operation in the event of a side collision. As a result, all doors may become locked during a collision, requiring additional time to rescue occupants.

3. Improvement Details

The driver's side door lock of all vehicles will be replaced with corrective parts, and the key operation method described in the owner's manual will be corrected.

As it will take time to supply the corrective parts, provisional measures will be carried out for customers who request it to prevent the doors from locking during a collision. These measures will render the key unusable for operating the door lock and restrict it to remote control operation only. Customers will then be notified once corrective parts have been prepared for replacement.