

March 14, 2019

Daihatsu Motor Kyushu Co., Ltd.  
Daihatsu Motor Co., Ltd.

## **Report on the Daihatsu Motor Kyushu Co., Ltd. Plant Fire**

Today at around 9:40 am, a fire occurred at Daihatsu Kyushu's Oita (Nakatsu) Plant 1. We would like to offer our sincerest apologies to residents living in the neighborhood of the plant, and to the many other people we have worried or inconvenienced. We would also like to take this opportunity to report on the details we currently know.

1. Date and time of fire: The automated fire alarm was activated at approximately 9:40 am on March 14, 2019
2. Location of fire: Daihatsu Motor Kyushu Co., Ltd. Oita (Nakatsu) Plant 1, Painting Plant,
3. Details of fire:  
**<Sequence of events>**  
9:40 am Automated fire alarm is activated  
The in-house fire-fighting team is dispatched  
9:58 am Nakatsu Fire Brigade and Nakatsu Police arrive; Nakatsu Fire Brigade commences fire-fighting operations  
One person is injured and sent to hospital  
14:26 pm Fire is officially extinguished
4. Effects of fire: One person was injured, and is currently receiving treatment at hospital. The fire did not spread to neighboring areas. The extent of facility damage—including the area destroyed by fire—is currently unknown.
5. Causes of fire: At present, the causes of the fire are unknown. Nakatsu Fire Brigade and Nakatsu Police are scheduled to conduct an inspection of the premises at 10 am tomorrow morning.
6. Effects on production: At present, the extent of damage caused by the fire is unknown; for this reason, we are still in the process of clarifying the effects on production.
7. Countermeasures: After the causes of the fire have been identified, we intend to implement countermeasures immediately.

We will issue a second report when points 5 to 7 above have been clarified or decided.